FIELD INSPECTION REPORT

			The state of the s	
Date of	Inspection: 17	7.12.2020	District: 10	animatica de la compania de la comp
Division	rision: East-1 Length (km): D			<u>k</u>
Name o	f the Road: P.O	hua Patalas	sa bhash bath to sal	and the second second
		MAINTENANCE	sa phosy park to sav	1010
Package		Andready and the second second second second second second	Road Id No.:	(APPENDAGE OF A COMPANY COMPAN
	f the Project:	Ongoing/Completed/Under Maintenance		Batherstein ber der Bereiten von Gestellen
Work is	a case of:	New Connectivity/	Up gradation/ Maintenance	
Sl. No. Parameter		Parameters to	・ 「「「「「「「「「」」」」「「「」」」「「「」」「「」」「「」」「「」」「「	Remarks
1.	Pavement			
a)	Road Junction condition			√s⁄U
b)	Condition of Surfacing			√\$∧U
c)	Riding Quality			J. Š/U
d)	Road Camber			√\$⁄U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Ves/No
f)	Contraction Joints provided or not (CC Pavement)			Yes/No
g)	Compaction of flank/slope & raincuts if any			Yes/No
2.	Cress Drainag	je .		
a)	Condition of head walls in Hume pipe culverts including its painting			√S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			√S/SRI/U
c)	Condition of railings/slab/approach for Bridges			√S/SRI/U
3.	Road Furniture			
3)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			Vés/No
4.	Compliance History			
a)	Status of ATR's & any others			
Overall F	Rating :		colos necesarios condense contense e se antes responsos contenses contentes contentes con tractorios contentes con tractorios	The Committee of the Co
· · · · · · · · · · · · · · · · · · ·		Satisfactory (S)		5
		Satisfactory but	requires Improvement (SRI)	
		Unsatisfactory (I	5)	

NAME:

DESIGNATION: