FIELD INSPECTION REPORT

	te of Inspection: 18 12 · 2020	District: Samastipur	
Division: RWD Dalsinghsarai Length(km): 0,64		340	
	me of Road: TOZ to Havi	2an talo.	
_	neme / Programme: MAINTENANCE	mmasy (G	eneral)
	kage No:	Road Id No:	
	tus of the Project: Ongoing/Completed/Under		
	rk is a case of: New Connectivity/ Up g	gradation/ Maintenance	
Sl. No	Parameters to be Checked		Remarks
1	Pavement		
a)	Road Junction Condition		3
b)	Condition of Surfacing		2
c)	Riding Quality		S
d)	Road Camber		S
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement		9
f)	Construction Joint provided or not(CC Pavement)		2
g)	Compaction of flank/slope & raincuts if any		3
2	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting		1
b)	Condition of Abutment & Wing walls , Slab in RCC culverts		1 A D
c)	Condition of railings/slab/approach for Bridge		
3	Road Furniture		
a)	Whether sign boards/information/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained		3
4	Compliance History		
a)	Status of ATR's & any others		No
	Overall Rating:		
	Satisfactory(S)		
	Satisfactory but requires	Improvement(SRI)	
	Unsatisfactory(U)		A BENCHMAN

Ramed Kung Sh

18 ·12 · 2020 (Signature)

NAME:

DESIGNATION: