## FIELD INSPECTION REPORT

District : Bhagalpur
Length (km): 2.4
to Čhandní Čhaunk vía Damodarpur
cy 2018
Road Id No.: 27321033620

Work is a case of : Upgradation

SI. No.	Parameters to be checked	Remarks	
1	Pavement		
a)	Road Junction condition	ÑÁ	
b)	Condition of Surfacing	NA	
c)	Riding Quality	NA	
d)	Road Camber	NA	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	NA	
f)	Contraction Joints provided or not (CC Pavement)	NA	
g)	Compaction of flank/slope & raincuts if any	NA	
2	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	NA	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	NA	
c)	Condition of railings/slab/approach for Bridges	NA	
3	Road Furniture		
a)	Whether sign board/informatory/cautionary Board/km & 200m stones/Pavement Road marking are provided and Maintained	Yes	
4	Compliance History		
a)	Status of ATR's & any others: Work has not been started as yet.		

Overall Rating	Satisfactory (S)	
	Satisfactory but requires Improvement (SRI)	NA
8	Unsatisfactory (U)	

NAME: KUMAR RAKESH

DESIGNATION: EXECUTIVE ENGINEER