

# FIELD INSPECTION REPORT

Date of Inspection : 18.12.2020 District: KAIMUR  
 Division : BHABUA Length (km): 2.54  
 Name of the Road: BHABUA DARAULI ROAD AKHLASHPUR MORE TO BHEKASH  
 Scheme/Programme: MAINTENANCE  
 Package No.: Road Id No.: 13141032419  
 Status of the Project: Ongoing Completed Under Maintenance  
 Work is a case of: New Connectivity/Up gradation/ Maintenance

| SL No. | Parameters to be checked                                                                                             | Remarks         |
|--------|----------------------------------------------------------------------------------------------------------------------|-----------------|
| 1.     | <b>Pavement</b>                                                                                                      |                 |
| a)     | Road Junction condition                                                                                              | ✓<br>SU         |
| b)     | Condition of Surfacing                                                                                               | ✓<br>SU         |
| c)     | Riding Quality                                                                                                       | ✓<br>SU         |
| d)     | Road Camber                                                                                                          | ✓<br>SU         |
| e)     | Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.                         | Yes No          |
| f)     | Contraction Joints provided or not (CC Pavement)                                                                     | Yes No          |
| g)     | Compaction of flank slope & raincuts if any                                                                          | Yes No          |
| 2.     | <b>Cross Drainage</b>                                                                                                |                 |
| a)     | Condition of head walls in Hume pipe culverts including its painting                                                 | ✓<br>S/SRI      |
| b)     | Condition of Abutment & Wing walls, Slab in RCC culverts                                                             | ✓<br>S/SRI      |
| c)     | Condition of railings/slab approach for Bridges                                                                      | ✓<br>S/SRI      |
| 3.     | <b>Road Furniture</b>                                                                                                |                 |
| a)     | Whether sign boards-informatory/cautionary Board km & 200m stones Pavement road markings are provided and maintained | Yes No ✓<br>SRI |
| 4.     | <b>Compliance History</b>                                                                                            |                 |
| a)     | Status of AFR's & any others                                                                                         |                 |

Overall Rating :

Satisfactory (S)

Satisfactory but requires Improvement (SRI)

Unsatisfactory (U)

SRI

Work in Progress

NAME: Er. Arun Kumar Mahato.

Signature  
 (Signature) 12.12.20