

FIELD INSPECTION REPORT

Date of Inspection :	District: KAIMUR
Division : BHABUA	Length (km): 4.39
Name of the Road: MANPUR SONDEHARA	
Scheme/Programme:	MAINTENANCE
Package No.:	Road Id No.: 10301502021
Status of the Project:	Ongoing Completed Under Maintenance
Work is a case of:	New Connectivity/Up gradation/ Maintenance

Sl No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓ S
b)	Condition of Surfacing	S ✓
c)	Riding Quality	S ✓
d)	Road Camber	S ✓
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes No } N.A
f)	Contraction Joints provided or not (CC Pavement)	Yes No }
g)	Compaction of flank slope & raincuts if any	Yes No ✓
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI } NA
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI }
c)	Condition of railings/slab approach for Bridges	S/SRI }
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board km & 200m stones Pavement road markings are provided and maintained	✓ Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)

Satisfactory but requires Improvement (SRI)

Unsatisfactory (U)

U

work is under progress

Arjun Kumar Machto
(Signature) (2 m)

NAME: Er. Arun Kumar Machto