

FIELD INSPECTION REPORT

Date of Inspection : 18.12.2020 District: KAIMUR
 Division : BHABUA Length (km): 1.297
 Name of the Road: PACHGAVAN BHABUA ROAD KUDRA
 Scheme/Programme: MAINTENANCE
 Package No.: Road Id No.: 10301502027
 Status of the Project: Ongoing Completed/Under Maintenance
 Work is a case of: New Connectivity/Up gradation/ Maintenance

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓ S U
b)	Condition of Surfacing	✓ S U
c)	Riding Quality	✓ S U
d)	Road Camber	✓ S U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No ✓
f)	Contraction Joints provided or not (CC Pavement)	Yes/No ✓
g)	Compaction of flank slope & raincuts if any	Yes/No ✓
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	✓ S SRI U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	✓ S SRI U
c)	Condition of railings/slab approach for Bridges	✓ S SRI U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board km & 200m stones Pavement road markings are provided and maintained	✓ Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	N.A.

Overall Rating :

Satisfactory (S) ✓

Satisfactory but requires Improvement (SRI)

Unsatisfactory (U)

Riding Surface is good.

NAME: Er. Arun Kumar Mahato

Armed
 (Signature) 18.12.20