FIELD INSPECTION REPORT BLCK- MYTLI fon j

| - | | 10/12/2020 | District: Madhepu | 180 | |
|--|--|--|---------------------------|----------------|--|
| Divis | | adhepyra | Length (km): 1:157 K | 5 | |
| | e of the Road: | Ichari To le | hari Bondha | | |
| - | me/Programme: | MAINTENANCE | | | |
| | age No.: | I Onnain I Committee | Road Id No.: | | |
| NAME AND ADDRESS OF THE OWNER, WHEN PERSON NAME AND ADDRESS OF THE O | s of the Project: | And in commence of the last of | d/Under Maintenance | | |
| SL No | | SET CHARLES AND A CONTRACT OF SECURIOR | Up gradation/ Maintenance | The All States | |
| 25. 3 | | Parsonaters to | be shedled | Remark | |
| 1. | The state of the s | | | | |
| a) . | Road Junction condition | | | S/U | |
| b) | Condition of Surfacing | | | _S/U | |
| c) | Riding Quality | | | SAU | |
| d) | Road Camber | | | LSAU | |
| e) | Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement. | | | Yes/No | |
| t) | Contraction Joints provided or not (CC Pavement) | | | Yes/No | |
| g). | Compaction of flank/slope & raincuts if any | | | Y-No. | |
| 2. | Cross Drainage | de la | | | |
| a) | Condition of head walls in Hume pipe culverts including its painting | | | S/SRI/U | |
|) | Condition of Abutment & Wing walls, Slab in RCC culverts | | | S/SRI/U | |
|) | Condition of railings/slab/approach for Bridges | | | SASTAU | |
| | Road Furniture | | | | |
| | Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained | | | | |
| | Compliance History | | | | |
| 5 | Status of ATR's & any others | | | NA | |

Overall Rating

| | - |
|---|---|
| Satisfactory (S) | - |
| Satisfactory but requires Improvement (SRI) | ~ |
| Unsatisfactory (U) | 4 |

