FIELD INSPECTION REPORT

	aspection:	7-12-2020	District: Natando	
Division	KKIO H	monut.	Length (km): 0.750 KM	140
	the Road: 67	shalbur Ho	but Probey Prope	I to to
	rogramme:	MAINTENANCE	70	
Package			Road Id No.:	
	the Project:		/Under Maintenance Ip gradation/ Maintenance	
NAME AND ADDRESS OF THE PARTY OF	a case of:		The state of the s	ANGLED SIZ
Sl. No.	Parameters to be checked			Remarks
1.	Pavement			
a)	Road Junction condition			S/U
b)	Condition of Surfacing			S/U
c)	Riding Quality			S/U
d)	Road Camber			S/U
e)	Whether free from defects such as visible cracks, exposed nggregates in case of CC Pavement.			Yes/No
f)	Contraction Joints provided or not (CC Pavement)			Yes/No
g) .	Compaction of flank/slope & raincuts if any			Yes/No
2	Cross Drains	ge .	1 4	
a)	Condition of head walls in Hume pipe culverts including its painting			S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/U
c)	Condition of railings/slab/approach for Bridges			S/SRI/U
3	Road Furniture			
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			Yes/No
4	Compliance	History		
a)	C	C's & any others		10

Overall Rating

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	U

(Signature)

NAME:

DESIGNATION:

Scanned with CamScanner