		FIELD INSPECT	ION REPORT	
				ombaren
Division: Chedia			Length (Km): - 1258	
Name of		SH74 to		
	/Programme :	MMGST SC	, ,	
Package No.: Road ID No.: - 3170841				30/3
Status of the Project : Ongoing/Completed/Under Maintenance				
Work is	a case of :	New Connectivity/Up	Gradation/ Maintenance	
SI. No.	Parameters to be ch			Remarks
1,	Pavement			
a)	Road Junction condition			Yes S
b)	Condition of Surfacing			2 64
c)	Riding Quality			Key S
d)	Road Camber			S
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes
f)	Contraction Joints provided or not (CC Pavement)			Yes
g)	Compaction of flank/slope & raincuts if any			Yes
2,	Cross Drainage			
a)	Condition of head walls in Hume pipe culverts including its painting			
b)	Condition of Abutment & Wing walls, Slab in RCC Culverts			
c)	Condition of railings/slab/approach for Bridges			
3,	Road Furniture			
a)	Whether sign board/informatory/cautionary Board/Km & 200m Stones/Pavement road markings are provided and maintained			NO, flank
4,	Compliance History			
a)	Status of ATR's & an	y others		
	Overall Rating :	Satisfactory (S) Satisfactory but requ Unsatisfactory (U)	ires improvement (SRI)	SRI
N	ote:- Board, roc regnisse	2 furniture /	ourting and Jungle Con	tling
	NAME:		77 4 Horanatur	~,
	DESIGNATION .			