FIELD INSPECTION REPORT

Name	Inspection: 17-12-2020 District HARNAUT Length	1413613.01	
Scheme	of the Rond: Tob to chaksund		Bigha
Package	Programme: Tot to chaksund	truction work	
Status	of the Project: Ongoing/Completed/Under N	d No.:	
Work			
SI. No.	New Connectivity/Up gradati	on/ Maintenance	
1.	Parameters to be checked		Remarks
	Pavement		
n)	Road Junction condition		√8/U -
b)	Condition of Surfacing	/.	S/UV
c)	Riding Quality		-8/U
d)	Road Camber		S/U V
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.		Yes/No U
0	Contraction Joints provided or not (CC Pavement)		Yes/No
g)	Compaction of flank/slope & raincuts if any		Yes/No V
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting		S/SRI/U~
b)	Condition of Abutment & Wing walls, Slab in RCC culverts		S/SRI/U
c)	Condition of railings/slab/approach for Bridges		S/SRI/U
3.	Road Furniture		Siskire
a) ·	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained		Yes/Not
4.	Compliance History		
a)	Status of ATR's & any others		

Overall Rating

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	11

(Signature)

NAME: A Jay KUM AR VERMA
DESIGNATION: JUNIOR Engineer.

Scanned with CamScanner