FIELD INSPECTION REPORT

Date of	Inspection: 18-12-2020 District: NALAND	A	
Division	HARNAUT Length (km): 10 Am 16		
Nameo	of the Road: SHEY burto Kathanburg via Ratanburg ATANDUA		
	The state of the s		
Package	Road Id No.:		
	f the Project: Ongoing/Completed/Under Maintenance		
	a case of: New Connectivity/Up gradation/ Maintenance		
SI. No.	Parameters to be checked	Remarks	
1.	Pavement	<u> </u>	
n)	Road Junction condition	S/Uv	
b)	Condition of Surfacing	S/U	
c)	Riding Quality	S/U J	
d)	Road Camber	₩ 87U	
c)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Ves/No	
Ŋ	Contraction Joints provided or not (CC Pavement)	Yes/No'L	
g)	Compaction of flank/slope & raincuts if any	Yes/No L	
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U	
c)	Condition of railings/slab/approach for Bridges	S/SRI/U	
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No	
40000	Compliance History		
a)	Status of ATR's & any others		

Overall Rating

T -
-
11

18-12-702C

(Signature)

NAME: A JAY KUMAR VERMA

DESIGNATION: JUNIOR Engineer