## FIELD INSPECTION REPORT

ate of Inspec	lion: 18-12-2020	District: Nalards	
ivision :	BitaroSharrf	Length (km): 1.628 RAV	
ame of the R		inathpur VR-22	
cheme/l'rogr	amme: MAINTENANCE	Pmssy	
ackage No.:		Road Id No.:	
tatus of the I	11.0	d/Under Maintenance	77
Vork is a cas		Up gradation/ Maintenance	Remarks
Sl. No.	Parameters to	be checked	Remarks
1. Pav	ement		
n) Ron	d Junction condition		S/U
b) Cor	idition of Surfacing		S/U
	ing Quality		S/U
	nd Camber		S/U
W	tether free from defects surgestes in case of CC Pavemen	ich as visible cracks, exposed	Yes/No
	ntraction Joints provided or not		Yes/No
	mpaction of flank/slope & raing		Yes/No
	oss Drainage		
a) Co	ndition of head walls in Hume	pipe culverts including its painting	S/SRI/U
	ondition of Abutment & Wing w		S/SRI/U
	ondition of railings/slah/approac		S/SRI/U
	ad Furniture		<del></del>
111	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained		Yes/No
74.5 C	impliance History		-
	atus of ATR's & any others		191

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

(Signature)

NAME: Arvind Kunga

DESIGNATION: Junior Regimen