FIELD INSPECTION REPORT Date of Inspection : 19-12-20 East Champaran Division: District: Charkia Length (Km):- <del>1242</del> 2.579 Name of the Road : Rampus to Bairiga. Koras Scheme/Programme: Package No.: Road ID No.: - 31708400310 Status of the Project : Ongoing/Completed/Under Maintenance Work is a case of : New Connectivity/Up Gradation/ Maintenance SI. No. Parameters to be checked Remarks 1, Pavement a) Road Junction condition b) Condition of Surfacing 5 c) **Riding Quality** d) 5 Road Camber Whether free from defects such as visible cracks, exposed aggregates in e) No case of CC Pavement. f) Contraction Joints provided or not (CC Pavement) Yes Yes g) Compaction of flank/slope & raincuts if any **Cross Drainage** 2, Condition of head walls in Hume pipe culverts including its painting SRI a) Condition of Abutment & Wing walls, Slab in RCC Culverts b) NA Condition of railings/slab/approach for Bridges c) Road Furniture 3, Whether sign board/informatory/cautionary Board/Km & 200m NO, Flanks Stones/Pavement road markings are provided and maintained a) Compliance History 4. Status of ATR's & any others a) Satisfactory (S) Overall Rating Satisfactory but requires improvement (SRI) SRI Unsatisfactory (U) Note- Hume fipe Culvert including painting & Jungle (villing por roud furnitur painting required . )

NAME:

**DESIGNATION:**