

FIELD INSPECTION REPORT

Date of Inspection : 18.12.20	District Nalanda
Division : 14259	Length (km): 1.51km
Name of the Road: To Komratu musali mairatti road to Baingai	
Scheme/Programme: MAINTENANCE	Maintenance HM63Y
Package No.:	Road Id No.:
Status of the Project: Ongoing/Completed/Under Maintenance	
Work is a case of: New Connectivity/Up gradation/ Maintenance	

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S
b)	Condition of Surfacing	S
c)	Riding Quality	S
d)	Road Camber	S
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Y No Y
f)	Contraction Joints provided or not (CC Pavement)	Y No Y
g)	Compaction of flank/slope & raincuts if any	Y No Y
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S RIU KI
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S RIU KI
c)	Condition of railings/slab/approach for Bridges	S RIU KI
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Y No NO
4.	Compliance History	
a)	Status of ATR's & any others	NO

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	

NAME:

Pradeep Kumar Arya
J.E

[Signature]
18.12.20
S. B. A. W.