

FIELD INSPECTION REPORT

Date of Inspection: 19-12-2020 District: Samastipur				
Division: RWD Dalsinghsarai Length(km): 143544				Lu
Nan	ne of Road: 204	8 to Damodar pur	Mahuli paswom Tol	a, Brahaman Jole,
Sch	eme / Programme:	MAINTENANCE		
Pacl	kage No:	MABARD	Road Id No:	
-	The second secon	ngoing/Completed/Under M	1aintenance	
	rk is a case of:	New Connectivity/ Up gra	adation/ Maintenance	
SI. No	Parameters to be Checked			Rema i.s
1	Pavement			
1)	Road Junction Condition			5
h)	Condition of Surfacing			5
0)	Riding Quality			5
1)	Road Camber			5
2)	Whether free from aggregates in case	5		
1)	Construction Joint provided or not(CC Pavement)			5
2).	Compaction of flank/slope & raincuts if any			5
2	Cross Drainage			5
1)	Condition of head walls in Hume pipe culverts including its painting			
))	Condition of Abutment & Wing walls, Slab in RCC culverts			
)	Condition of railings/slab/approach for Bridge			
3	Road Furniture			
)	Whether sign boards/information/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			3
	Compliance History			
,	Status of ATR's & a	as		
	Overall Rating :			
	coveran Kating	Satisfactory(S)		1 .8
		Satisfactory but requires In	nprovement(SRI)	
		Unsatisfactory(U)		

And preen

(N) 101

NAME.