FIELD INSPECTION REPORT

Date of Inspection	- 1	Platetate Alada A			
Date of Inspection : 1	8/12/2020	District: Nalanda			
Dission: Babanakai		Longth (km): 1. UDKM			
Name of the Road: 1869 - 6061 To RATORUA (VRUI)					
Scheme/Programme:	MAINTENANCE	PMGSY			
Package No.:		Road Id No.:			
Status of the Project:	Ongoing/Completed/Under Maintenance				
Work is a case of:	New Connectivity/Up gradation/ Maintenance				

SI. No.	Parameters to be checked	Remarks	
, 1 .	Pavement		
a)	Road Junction condition	S/U	
b)	Condition of Surfacing		
c)	Riding Quality		
d)	Road Camber	S/U '	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No	
f)	Contraction Joints provided or not (CC Pavement)	Yes/No	
g)	Compaction of flank/slope & raincuts if any	Yes/No	
2	Cross Drainage	3. **	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U	
c)	Condition of railings/slab/approach for Bridges	S/SRI/U	
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No	
4.	Compliance History		
a)	Status of ATR's & any others	No	

Overall Rating :

Satisfactory (S)	-
Satisfactory but requires Improvement (SRI)	S
Unsatisfactory (U)	

NAME: Mucesheaday DESIGNATION: J. E.