FIELD INSPECTION REPORT

	- In the factor of the second	
	spection: 17-19-90 90 District: Malanda	
Division:	RWD Hornaut Length (km): 1.840 km	- 10
i di	the Rand: Propolar in chande Throughous	past to
	rogramme: MAINTENANCE	
Package		
	the Project: Ongoing/Completed/Under Maintenance a case of: New Connectivity/Up gradation/ Maintenance	
	Same with	Remarks
Sl. No.	Parameters to be checked	Remarks
1.	Pavement	atherin b
a)	Road Junction condition	S/U
b)	Condition of Surfacing	S/U
c)	Riding Quality	S/U
d)	Road Camber	S/U
c)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	NO

Overall Rating

		7
Satisfactory (S)	S	
Satisfactory but requires Improvement (SRI)		
Unsatisfactory (U)		

(Signature)

NAME:

DESIGNATION:

Scanned with CamScanner