

FIELD INSPECTION REPORT

Date of Inspection: 19.12.2020		District: Samastipur
Division: RWD Dalsinghsarai		Length(km): 2.615km
Name of Road: 1038 to Dalsingh Tola		
Scheme / Programme: MAINTENANCE		
Package No: MM684	Road Id No:	
Status of the Project: Ongoing/Completed/Under Maintenance ✓		
Work is a case of:		New Connectivity/ Up gradation/ Maintenance

Sl. No	Parameters to be Checked	Remarks
1	Pavement	
a)	Road Junction Condition	S
b)	Condition of Surfacing	S
c)	Riding Quality	S
d)	Road Camber	S
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement	S
f)	Constraction Joint provided or not(CC Pavement)	
g)	Compaction of flank/slope & raincuts if any	
2	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	-
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	-
c)	Condition of railings/slab/approach for Bridge	-
3	Road Furniture	
a)	Whether sign boards/information/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	S
4	Compliance History	
a)	Status of ATR's & any others	N.

Overall Rating :

Satisfactory(S)	S
Satisfactory but requires Improvement(SR1)	
Unsatisfactory(U)	

NAME:

[Signature]
[Signature]

[Signature]
 19.12.2020
 (Signature)