## FIELD INSPECTION REPORT

Date of Inspection:	7-12-2020	District: NALANDA
Division: Harraut		Length (km): 1.300
Name of the Rond: N	1.4-31 Ke DW	asi Na Bigha TO VILLAGE BAMOCH
	MAINTENANCE	
Package No.:		Road Id No.:
Status of the Project:	Onguing/Completed/Under Maintenance	
Work is a case of:	New Connectivity/Up gradation/ Maintenance	

l. No.	Parameters to be checked	Remarks	
1.	Pavement		
a)	Road Junction condition		
b)	Condition of Surfacing		
c)	Riding Quality		
d)	Road Camber		
c)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.		
ŋ	Contraction Joints provided or not (CC Pavement)		
g)	Compaction of flank/slope & raincuts if any		
<b>2</b> ;	Cross Drainage	S/ŞR1/U	
a)	Condition of head walls in Hume pipe culverts including its painting		
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	√S/SRI/U	
c)	Condition of railings/slab/approach for Bridges	S/SRI/U	
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No	
<b>TA.</b>		* , *	
8)	Status of ATR's & any others		
-,	이번 나는 사람들은 사람들이 되었다. 그는 그는 사람들은 사람들이 되었다면 하는 것이 되었다면 하는 것이 없는데 하는데 하는데 하는데 하는데 하는데 하는데 하는데 하는데 하는데 하		

Overall Rating

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	(SRI)
Unsatisfactory (U)	

My Soy D

(Signature)

DESIGNATION: A-E

: