

FIELD INSPECTION REPORT

Date of Inspection :	18.12.20	District	Nalanda
Division :	Diyala Bertha I-II SA	Length (km):	2.7 km
Name of the Road:	Diyala Bertha road to near Bixi per college to Kusa per NDB/Bricks		
Scheme/Programme:	MAINTENANCE Maintenance		
Package No.:		Road Id No.:	
Status of the Project:	Ongoing/Completed/Under Maintenance	Under Maintenance	
Work is a case of:	New Connectivity/Up gradation/ Maintenance	Maintenance	

SL No.	Parameters to be checked	Remarks
1.	Pavement	S
a)	Road Junction condition	S
b)	Condition of Surfacing	S
c)	Riding Quality	S
d)	Road Camber	S
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	No Yes
f)	Contraction Joints provided or not (CC Pavement)	No Yes
g)	Composition of flank/slope & raincuts if any	No Yes
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S RI S
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S RI S
c)	Condition of railings/slab/approach for Bridges	S RI S
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	No Yes
4.	Compliance History	
a)	Summary of ATR's & any others	NO

Overall Rating :

Satisfactory (S)	Satisfactory
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

NAME:

Pradip Kumar Singh
J.G

Am
18.12.20
S. ELAWD