## FIELD INSPECTION REPORT

Date of	Inspection: 2	1.12.2023 Disti	ict: W. Champ	grown		
Divisio	n: RWD work	Div. Bagaka-1 Len	gth (km): 9.74	1 km	1	
Name e	of the Road: PW	D Real-Huradala	, manufacture and a second			
	e/Programme:	MAINTENANCE				
		E/BACy/20-0004 Roa	d Id No.: 3180	9102	026	
	of the Project:	Ongoing/Completed/Unde		-		
Work i	s a case of:	New Connectivity/Up grad	lation/ Maintenance	New	Mainter	ance
SI. No.	No. Parameters to be checked Remarks				Remarks	
1.	Pavement					
8)	Road Junction	Road Junction condition				
b)	Condition of Surfacing					<u> </u>
c)	Riding Quality					]
d)	Road Camber					] '
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.					
Ŋ	Contraction Joints provided or not (CC Pavement)					۷. ا
g)	Compaction of flank/slope & raincuts if any					7-N
2.	Cross Drainage					V
a)	Condition of head walls in Hume pipe culverts including its painting					
b)	Condition of A	Condition of Abutment & Wing walls, Slab in RCC culverts				
c)	Condition of ra	ilings/slab/approach for Br	idges			1
3.	Road Furniture					] [
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained					
4.	Compliance History					
a)	Status of ATR's	& any others		NO	. 120	

Overall Rating

Satisfactory (S) Satisfactory but requires Improvement (SRI) Unsatisfactory (U)

Notre Desured (Si

(Signature) 21-12,2020)

DESIGNATION: Executive Engineer