## FIELD INSPECTION REPORT

		FIELD INSPECTI	ON REPORT		
ate of In	spection: 21	12:2020 1	Intrict: Natonda		
Division : D'Lacola I			Length (km): 1.7 Fin		
	he Rond: A/	MAINTENANCE M.	ia Mills		
	rogramme:	MAINTENANCE M.	R-3054		
ackage l		1 18	ORU 10 (10		
tatus of	the Project:	Ongoing/Completed/Un	nder Maintenance		
Work is a case of: New Connectivity/Up grada		radation Maintenance	Remarks		
SI. No.	Parameters to be checked				
1.	Pavement			S/U S	
a)	Road Junction condition			S/U.S	
b)	Condition of Surfacing			√S/U B	
c)	Riding Quality			S/U.S	
d)	Road Camber			Yes/No/4	
c)	Whether the SCC Povement				
n	Contraction Joints provided or not (CC Pavement)			Yes/No -	
g)	Compaction of flank/slope & raincuts if any  Yes/N				
2.,	Cross Drainage				
a)	Condition of head walls in Hume pipe culverts including its painting			S/SRI/U V	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts S/SRD			S/SRI/U	
c)	Condition of railings/slab/approach for Bridges S/SRI/U			S/SRI/U	
3.	Road Furniture			. 1	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained				
Z.4.5	Compliance History				
a)	Status of ATR's & any others				

Overall Rating

Satisfactory (S)	_
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	_

NAME: Rana Baroun Krlingh DESIGNATION: Executive Enfinces.

Scanned with CamScanner