

FIELD INSPECTION REPORT

old MIR 3054

Date of Inspection : 21/12/2020		District: Bhojpur
Division : N.W.D. Jangalishpur		Length (km): 9.70 km
Name of the Road: Gure Bahora pur road umreon ganiga Chaki, Nalla ranga		
Scheme/Programme: MAINTENANCE		
Package No.:		Road Id No.: 10401708052
Status of the Project:	Ongoing/Completed/Under Maintenance	
Work is a case of:	New Connectivity/Up gradation/ Maintenance	

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U ✓
b)	Condition of Surfacing	S/U ✓
c)	Riding Quality	S/U ✓
d)	Road Camber	S/U ✓
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No ✓
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	Yes

Overall Rating :

Satisfactory (S)

Satisfactory but requires Improvement (SRI)

Unsatisfactory (U)

(U)

Remarks: Appearance of patches, pots, edge breakage, depression throughout the length at irregular intervals. Exposed aggregates in RCC. Deficient Road furniture etc.

(Signature)

21/12/20
EE

NAME:

Rectification done or not : Not
Rectification started or not : Not
Notice issued or not - Yes

(N.A. ISHRAAT)