## FIELD INSPECTION REPORT

te of Inspects	20.12.2020	· District: Purmen	
visigna	Baisi	Length (km): 1.096 KM .	nthal tola
me of the Ra	all a Bhalcha	ri Manimelhan to Kunsela Sar E Marsy	
hemo Progra	MAINTENANC	Road Id No.:	
ckage No.: atus of the Pr	Ongoing/Compl	eted/Under Maintenance	
ork is a case	New Connectivi	ty/Up gradation/ Maintenance	Maria Maria
CONTRACTOR OF THE PARTY OF	Name of the last o	s to be checked	
Contraction of the last of the	ment	• • •	S/U
	Road Junction condition		
	St. Charles and the state of th		
FAR (1) 1-19.00 (10)	Condition of Surfacing		
- 1	Riding Quality		
d) Rose	Road Camber  Whether free from defects such as visible cracks, exposed		
c) Who	egates in case of CC Pave	ment.	Yes/No
f) Con	Contraction Joints provided or not (CC Pavement)		
	Compaction of flank/slope & raincuts if any Yes/		Yes/No
			ARM M
原品高層	Condition of head walls in Hume pipe culverts including its painting		
a) Cor	Condition of head waits in Hume pape of the RCC culverts		
b) Cor	Condition of Abutment & Wing walls, Slab in RCC culverts  Condition of railings/slab/approach for Bridges		S/SRI/U
		proach for Bridges	
3. R6	Road Furniture		
a) Wi	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained		Yes/No
W. 100	mpliance History		-
	atus of ATR's & any other	ns .	
			1 9
Overall Rati	ng Satisfacto		2

400	9
Satisfactory (S)	T S DELETY
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

(Signature)

NAME:

R.B. Simpl

DESIGNATION

J.E