## FIELD INSPECTION REPORT

D	ate of Inspection: 21.12 2.00	PORT
D	Vision: RWD Dalsinghas District: Samasti	O1t1
Na	me of Post	the Control of the Co
Sc	hama / D	20 Kim
Pa	ckage No: MAINTÉNANCE PMGCY	Khedy farn.
Sta	itus of the Project: Ongoing/Co	
Wo	orle in Ongoing/Completed/Under Maintenance	
SI.	New Connectivity/ Up gradation/ Maintenance	
No	Parameters to be Checked	
1	Pavement	Remarks
a)	Road Junction Condition	
b)	Condition of Surfacing	2
c)	Riding Quality	C
d)		C
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement	2
f)	Constraction Joint provided or not(CC Pavement)	2
g)	Compaction of flank/slope & raincuts if any	2
2	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	
c)	Condition of railings/slab/approach for Bridge	
3	Road Furniture	
a)	Whether sign boards/information/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	2
4	Compliance History	
a)	Status of ATR's & any others	

Overall Rating:

The second secon	FHIM-Spice Inc.	
Satisfactory(S)	5	
Satisfactory but requires I		
Unsatisfactory(U)		

Signature) 48

NAME: Pseu Chandre Guplo DESIGNATION: Asst. Engineer Morwy,