FIELD INSPECTION REPORT

tate of Inspection 1 21.72.2000			District: Sheikhpung	ray day
ivision: Sheekenbroa		Abraa	Length (km): 0 : 439 KM	
ame of	the Road:	Saturna More	se Datuara Path	r ere illinoise en en
cheme/	Programme:	MAINTENANCE		Stage - 20
ackage	No.:	,	Road Id No.:	
			pleted/Under Maintenance	
Vork is a case of:		New Connectivity/Up gradation/ Maintenance		
SL No.	181	Parameters t	a be checked	Remarks
1.	Pavement		1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1	
a)	Road Junction	condition		S/U/
b)	Condition of Surfacing			S/U
c)	Riding Quality			,8/U/
d)	Road Camber :			\$/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes/No
Ŋ	Contraction Joints provided or not (CC Pavement)			Yes/No
g)	Compaction of flank/slope & raincuts if any			Yes/No
	Cross Drain			ta .
3)	Condition of head walls in Hume pipe culverts including its painting			S/SPI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/U
c)	Condition of railings/slab/approach for Bridges			S/SRI/U
3.	Road Furniture			
a) .	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			
4,	Compliance History			
a)	Status of AT	R's & any others		the species depleted and the

Overall Rating

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	September 1990
Unsatisfactory (U)	33

(Signature)

NAME: PANKAJ KUMAR JE, ARIYAR!