## FIELD INSPECTION REPORT

A CAN TO STATE OF THE PARTY OF	
Islan . A District: West Chan	barren
	km
Smc/Program PMasy Real Bairathi to Balkahar	5-6
INGE NO.: MAINTENANCE- MM WY	
Road Id No.:	
de n como de la complete de la compl	
n Connectivity/Up gradation/ Maintenance	A COLUMN TO PROPERTY.
Parameters to be checked	Remarks
Road Junction condition	SAU
Condition of Surfacing	SAY
Riding Quality	S/T
	SAT
Barbanes in case of CC Pavement.	yes/No
	Yes/No
Compaction of flank/slope & raincuts if any	Yes/No
Cross Drainage	
Condition of head walls in Hume pipe culverts including its paint	ing S/SRI/U
Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
Condition of railings/slab/approach for Bridges	S/SRI/U
toad Furniture	
Whether sign boards/informatory/cautionary Board/km & 20 ones/Pavement road markings are provided and maintained	0m Yes/No
ompliance History	
atus of ATR's & any others	Colored by your burney .
	Re of the Road: PM GAY Prod Borrally to Bo

Overall Rating

Satisfactory (S)
Satisfactory but requires Improvement (SRI)
Unsatisfactory (U)

(Signature)

NAME: ~

DESIGNATION:

Rvo