## FIELD INSPECTION RUPORT

			District:	
Date of Inspection: 22-12.200			Length (km):	
	: Bullian			
	The second residence of the se	MAINTENANCE	Road Id No.	brat.
Package		Longoing/Complete	d/Under Maintenance	
The section Name of Street, St	the Project: a case of:	New Connectivity	Op gradation/ Maintenance	
Sl. No.	a case or:	Parameters to	be checked	Remarks
1.	Pavement			
a)	Road Junction condition			S/U
b)	Condition of Surfacing			S/U
c)	Riding Quality			§/U
d)	Road Camber			S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			
Ŋ	Contraction Joints provided or not (CC Pavement)			Yes/No
g)	Compaction of flank/slope & mincuts if any  Yes/N			Yes/No
2.	Cross Drainage			
a)	Condition of head walls in Hume pipe culverts including its painting S/SRI/			
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			s/sri/U
c)	Condition of railings/slab/approach for Bridges  S/SR			S/SRI/U
3.	Road Furniture			
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			
4.	Compliance History			
a)	Status of ATR's & any others			1

Overall Rating

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	U

(Signature)

NAME: paterda Assey

DESIGNATION: J.E