FIELD INSPECTION REPORT

Inspection: 21 12 2020 District: Samuships	- 600
n: Balia Length (km): 3.0 Um	72
	anye 1
AT LUCE WALLES	
e No.:	
of the Project: Ongoing Completed/Under Maintenance	
	Remarks
Parameters to be checked	Remarks
Pavement	
Road Junction condition	U S/U
Condition of Surfacing	U S/U
	U S/U
	12-S/U S
Whether free from defects such as visible cracks, exposed	√Yes/No
	✓Yes/No
	Yes/No
Compaction of flank/slope & famcus it any	, #11
Cross Drainage	G/ODIA!
Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
Condition of railings/slab/approach for Bridges	S/SRI/U
그는 그 그는 그는 그들은 그들은 사람들이 되는 것이 없었다. 그 가장이 되는 것이 없는 것이 없는데 없는데 없는데 없다면	
to the formatory/cautionary Board/km & 200m	Yes/No
	No
Status of ATR's & any others	100
֡	In: Balia Length (km): 3.0 Man of the Road: NM-3 to Danaula Phulw Programme: MAINTENANCE Old Maintenance of the Project: Ongoing Completed/Under Maintenance Road Id No.: Ongoing Completed/Under Maintenance Parameters to be checked Pavement Road Junction condition Condition of Surfacing Riding Quality Road Camber Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement. Contraction Joints provided or not (CC Pavement) Compaction of flank/slope & raincuts if any Cross Drainage Condition of head walls in Hume pipe culverts including its painting Condition of Abutment & Wing walls, Slab in RCC culverts Condition of railings/slab/approach for Bridges Road Furniture Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained Compliance History

Overall Rating

Satisfactory (S)	7
Satisfactory but requires Improvement (SRI)	*
Unsatisfactory (U)	U

Sami ULL (Signature) 21/12/2020

NAME: SAMIR Lumar

DECICNATION. E.E