

FIELD INSPECTION REPORT

Date of Inspection:	21/11/2020	District: Madhya Pradesh
Division:	Udage, Rangoan	Length (long): 9.80
Name of the Road:	Repair of road from RD 106 Buland to 106 and 107	
Scheme/Programme:	MAINTENANCE	
Package No.:		Road Id No: 91009808045
Status of the Project:	Ongoing/Completed/Under Maintenance	
Work is in case of:	New Connectivity/Up gradation/ Maintenance	

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U
b)	Condition of Surfacing	S/U
c)	Riding Quality	S/U
d)	Road Camber	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No N/A
f)	Contraction Joints provided or not (CC Pavement)	Yes/No N/A
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	U

many pot-patches have been found. The road is damaged in some portions due to passing flood. The work has not been started by the agency.

Wan
21/11/2020
(Signature)

NAME: SANJEEV Kumar

DESIGNATION: EXECUTIVE ENGINEER
CE-300, RWD, Patna