

MMGSY (SC)

FIELD INSPECTION REPORT

Date of Inspection :	16.12.2020	District:	Su/sant
Division :	NH 57	Length (km):	5.150
Name of the Road:	NH 57 - Mandel Tola Hote Kuye, Kore Tola Hote Kuye Pratapganj Simzali Road Premal ghen Tau		
Scheme/Programme:	MAINTENANCE ✓		
Package No.:	Road Id No.:		
Status of the Project:	Ongoing/Completed/Under Maintenance ✓		
Work is a case of:	New Connectivity/Up gradation/ Maintenance ✓		
Sl. No.	Parameters to be checked	Remarks	
1.	Pavement	S/U ✓	
a)	Road Junction condition	S/U ✓	
b)	Condition of Surfacing	S/U ✓	
c)	Riding Quality	S/U ✓	
d)	Road Camber	S/U ✓	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No ✓	
f)	Contraction Joints provided or not (CC Pavement)	Yes/No ✓	
g)	Compaction of flank/slope & raincuts if any	Yes/No ✓	
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U ✓	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U N-A	
c)	Condition of railings/slab/approach for Bridges	S/SRI/U N-A	
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No ✓	
4.	Compliance History		
a)	Status of ATR's & any others	No	

Overall Rating :

Satisfactory (S)	—
Satisfactory but requires Improvement (SRI)	—
Unsatisfactory (U)	U

NAME: Mangal Mandal

DESIGNATION: Junior Engineer

16/12/2020
(Signature)
pratapganj