## FIELD INSPECTION REPORT

Date of Inspection : 18-12 - 2020			District: Asaria .		
Division: Asques:  Name of the Road: Jacugator to d.			Length (km): 2.486 ·		
Name of	the Road: Jo	ingaion to dhang	pawa via sola.		
Scheme/	Programme:	MAINTENANCE			
Package No.:			Road Id No.:		
			/Completed/Under Maintenance		
Work is a case of:		New Connectivity/Up gradation/ Maintenance			
Sl. No.	CW O	Parameters to be ch	ecked	Remarks	
1.	Pavement				
a)	Road Junction condition			<b>√87U</b>	
b)	Condition of Surfacing			SU	
c)	Riding Quality			<b>√8/U</b>	
d)	Road Camber			SPU	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Ycs/Na	
f)	Contraction Joints provided or not (CC Pavement)			Yes/No	
g)	Compaction of flank/slope & raincuts if any			Yes/No	
2.	Cross Drainage				
a)	Condition of head walls in Hume pipe culverts including its painting			S/SP4/U	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			S∕SRI/U	
c)	Condition of railings/slab/approach for Bridges			-S/SRI/U	
3.	Road Furniture			190	
a) <sub>-</sub> -	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			Yes(No	
4.	Compliance History			· Margar	
a)	Status of AT	R's & any others			

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	(U)

(Signature)

NAME: Prince pr. yeulan