## FIELD INSPECTION REPORT

Date of Inspection: 16-12-2020			District: Madhubani	
Divisio			Length (km): 0 - 236 km	
	The second secon	ID stad Bank chan	ok se purman tol Manmohan	tak.
	e/Programme:	MAINTENANCE	MMGSY	
Package No.:			Rond Id No.:	
Cintae or the many		Ongoing/Completed/Under Maintenance  New Connectivity/Up gradation/ Maintenance		
The state of the s	a case of:	THE RESERVE THE PARTY OF THE PA	CARLINATED BODY 1 - MATERIAL PROPERTY SERVICES FOR THE SE	Carrier and State of Comme
SI. No.	Parameters to be checked			Remarks
1.	Pavement			
a)	Road Junction condition			<b>\$/U</b>
b)	Condition of Surfacing			√\$/U
c)	Riding Quality			√S/U
d)	Road Camber			√S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			-Yes/No
f)	Contraction Joints provided or not (CC Pavement)			Yes/No
g)	Compaction of flank/slope & raincuts if any			Yes/No
2.	Cross Drainag	<b>J0</b>		10 10 10 10 10 10 10 10 10 10 10 10 10 1
a)	Condition of head walls in Hume pipe culverts including its painting			S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/U
c)	Condition of railings/slab/approach for Bridges			S/SRI/U
3.	Road Furniture			
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			Yes/No
4.	Compliance History			
a)	Status of ATR's & any others			

Overall Rating

Satisfactory (S)
Satisfactory but requires Improvement (SRI)
Unsatisfactory (U)

(Signature) JE

NAME: Chitsenjan Rothul

DESIGNATION: JE