FIELD INSPECTION REPORT

	ate of Inspection: 22.12.2020 Disti	rict: Samastipur
Di	Vicione DIVID Date	th(km): 3 + 027 K.m
Na	me of Road: LOTZ-SH to Bangar	(VR72)
Sc	heme / Programme: MAINTENANCE PMG-17	
Pa	aleace No.	Id No:
Sta	tus of the Project: Ongoing/Completed/Under Maintenance	e
Wo	ork is a case of: New Connectivity/ Up gradation/ Ma	
SI. No	Parameters to be Checked	Remarks
1	Pavement	Note the state of
a)	Road Junction Condition	2
b)	Condition of Surfacing	e
c)	Riding Quality	6
d)	Road Camber	<u> </u>
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement	5
f)	Construction Joint provided or not(CC Pavement)	2
g)	Compaction of flank/slope & raincuts if any	
2	Cross Drainage	
1)	Condition of head walls in Hume pipe culverts including its painting	2
) (Condition of Abutment & Wing walls, Slab in RCC culver	rts C
	Condition of railings/slab/approach for Bridge	
- 1	Road Furniture	
V S1	Whether sign boards/information/cautionary Board/km & 2 cones/Pavement road markings are provided and maintaine	00m d
C	ompliance History	
St	atus of ATR's & any others	
		- 1.4. MIL.

Overall Rating:

)	
nt requires Improvement(SRI)	
(U)	
(U)	•

(Signature)

NAME: Psey chardles Emple DESIGNATION: A Morrows