


# FIELD INSPECTION REPORT

Date of Inspection: 22.12.2020		District: Samastipur
Division: RWD Dalsinghsarai		Length(km): 1.320 Km
Name of Road : L029-NH to Byaspur (VR-29)		
Scheme / Programme: MAINTENANCE		
Package No: BR 30R 516	Road Id No:	
Status of the Project: Ongoing/Completed/Under Maintenance		
Work is a case of:	New Connectivity/ Up gradation/ Maintenance	

Sl. No	Parameters to be Checked	Remarks
1	<b>Pavement</b>	
a)	Road Junction Condition	S
b)	Condition of Surfacing	S
c)	Riding Quality	S
d)	Road Camber	S
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement	S
f)	Constraction Joint provided or not(CC Pavement)	S
g)	Compaction of flank/slope & raincuts if any	S
2	<b>Cross Drainage</b>	
a)	Condition of head walls in Hume pipe culverts including its painting	S
b)	Condition of Abutment & Wing walls , Slab in RCC culverts	S
c)	Condition of railings/slab/approach for Bridge	S
3	<b>Road Furniture</b>	
a)	Whether sign boards/information/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	S
4	<b>Compliance History</b>	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory(S)	3
Satisfactory but requires Improvement(SRI)	
Unsatisfactory(U)	

  
 (Signature) 22/12/20

NAME:

Hem Chandra Gupta  
 Asst. Engineer