FIELD INSPECTION REPORT

Date of Inspection :	2 10 0000	District	
Division :	9-12-2020	District: Sitamanhi	
Tribion; Del com d		Length (km): 3-71	
Name of the Road:	hanua to		
Scheme/Programme:	MAINTENANCE	sugmain.	
Package No.:	I MAINTENANCE		
		Road Id No.: 31608008028	
Status of the Project:	Ongoing/Completed/Under Maintenance		
Work is a case of:	New Connectivity (1)		
The state of the s	New Connectivity/Up gradation/ Maintenance		

Sl. No.	Parameters to be checked		
1,	Pavement	Remarks	
a)	Road Junction condition	0.01	
b)	Condition of Surfacing	S/U	
c)	Riding Quality	S/U/	
d)	Road Camber	S/U/	
		S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No	
f)	Contraction Joints provided or not (CC Pavement)	Yes/No	
g)	Compaction of flank/slope & raincuts if any	Yes/No	
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U	
c)	Condition of railings/slab/approach for Bridges	S/SBA/U	
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No	
4.	Compliance History		
a)	Status of ATR's & any others		

Overall Rating

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	U

La Conforce (Signature)

NAME: CAZAN PRASIDO DESIGNATION: E.E.