FIELD INSPECTION REPORT

and the second of the	15. No. 14. No. 15. N	The second secon	
	Inspection: 23-12-2020 District: west chami	29204	
Divisio	n: R. up. Muks pin Augela-Length (km): 1.130KIV	The second secon	
Name o	of the Road: Kathar II Whalisa hall		
Scheme	Programme: MAINTENANCE		
Packag	e No.: RM/WE/BAY/19/003 Road Id No.: 3180910	2039	
A VISE WALL AND A	of the Project: Ongoing/Completed/Under Maintenance New Connectivity/Un gradation/ Maintenance (19)		
	A Prantice Manuel Manuel Press		
SI. No.	Parameters to be checked	Remarks	
1.	Pavement		
a)	Road Junction condition	3	
b)	Condition of Surfacing	S	
c)	Riding Quality	2	
d)	Road Camber	S	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.		
f)	Contraction Joints provided or not (CC Pavement)		
g)	Compaction of flank/slope & raincuts if any	- yel	
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	S	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts		
c)	Condition of railings/slab/approach for Bridges		
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	yes	
4.	Compliance History - HO	-	
1)	Status of ATR's & any others	[4]	

Overall Rating

Satisfactory (S)	2
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	40.1%

NAME: Ratnesh POSWAM

DESIGNATION: - Executive Engineer