## FIELD INSPECTION REPORT

Date of	Inspection: 2	3.12.2020	District: Nalando		
Division: Hilla			Length (km): 4.8 K		
			Road to Mahmudda	7	
	Programme:	MAINTENANCE	MR-New Maintename Po	Viy2018	
Package No.:			Road Id No.:		
	f the Project:	_	/Under Maintenance		
	n case of:		p gradation/ Maintenance -		
SI. No.	Parameters to be checked			Remarks	
1.	Pavement				
n)	Road Junction condition			SS/US	
b)	Condition of Surfacing			45/US	
c)	Riding Quality			YS/US	
d)	Road Camber			S/U S	
c)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.				
f)	Contraction Joints provided or not (CC Pavement)			Yes/No -	
g)	Compaction of flank/slope & raincuts if any			Yes/NoVa	
2.	Cross Drainag	ge .			
a)	Condition of head walls in Hume pipe culverts including its painting			S/SRI/USET	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/U	
c)	Condition of railings/slah/approach for Bridges			S/SRI/U	
3.	Road Furniture				
B)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained  Yes/I			Yes/No	
4.50	Compliance History				
a)	Status of ATR's & any others				

Satisfactory (S)	_
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	

NAME: Rana Boson Kumor Singh.
DESIGNATION: Exceptive Enfineer.

Scanned with CamScanner