FIELD INSPECTION REPORT

Date o	f Inspection: 2	3/12/2020	District: Madhefrina	egenetarionestroitorempione apresió com
Divisio	Division: Madhepura		Length (lon): 2.50	
Alleganisma ministration may	of the Rondi C	hondanfatli	to Epparha	
Committee of the State of the S	e/Programme:	MAINTENANCE		and the second s
Philippine and the second	ge No.:		Road Id No.: 21004700	821
elements de l'establishe de l'	of the Project:		/Under Maintenance	
The second secon	and the state of t	The second secon	Jp gradation/ Maintenance	
Sl. No.		Parameters to	be checked	Remarks
1.	Pavement			
a)	Road Junction condition			S/U
b)	Condition of Surfacing		S/U	
c)	Riding Quality		S/U	
d)	Road Camber		S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes/No
f)	Contraction Joints provided or not (CC Pavement)			Yes/No.
g)	Compaction of flank/slope & raincuts if any			Yes/No
2.	Cross Drainage			
a)	Condition of head walls in Hume pipe culverts including its painting			S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/U
c)	Condition of railings/slab/approach for Bridges			S/SRI/U
3.	Road Furniture			
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			Yes/No
4	Compliance His	tory		
a)	Status of ATR's	& any others		

Overall Rating

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	

The agency how started the w section work.

NAME:

SANDER KUMAR

DESIGNATION: EXECUTIVE CONGINEER

CE-3 dft; Pensy Portion