FIELD INSPECTION REPORT

Date of Inspection: 18-12 2020			District: 13anka	
Division: Banka J			Length (km): 1.247K.H.	
		nka Kateriya Pu	VORCED MOHOSPUT PMGSY R	00,140 193
and the state of the state of	e/Programme:	MAINTENANCE	the state of the s	
Package No.:		Ongaina/Camplet	Road Id No.:	
Status of the Project: Work is a case of:		Ongoing/Completed/Under Maintenance New Connectivity/Up gradation/ Maintenance		
SI No.		Parameters to be checked Remarks		
1	Pavement			
a)	Road Junction	∵ S/U		
b)	Condition of Surfacing			√8/U
c)	Riding Quality			√S/U
d)	Road Camber			~8/U
e)	Whether free aggregates in c	Yes/No		
f)	Contraction Jo	Yes/No		
g)	Compaction of	Yes/No		
2	Cross Drainag			
a)	Condition of h	S/SRI/U		
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/U M
c)	Condition of railings/slab/approach for Bridges			S/SRI/U A
3.1	Road Furniture			
a)	Whether sign stones/Pavement	Yes/No		
4.	Compliance H			
a)	Status of ATR's & any others			NO

Overall Rating

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

(Signature)

NAME: Ashok Kumar Sluba.

DESIGNATION: Junior Engineer