FIELD INSPECTION REPORT

		TION RISTORY	
spection: 2	2.12.20	District: Lalela Can	
RWDI	alo ha Cani		
the Road: KI	hutha week		ayat Bh
Programme:	MAINTENANCE	986	-
No.:		Road Id No.:	
	Ongoing/Completed	/Under Maintenance	
a case of:	New Connectivity/U	p gradation/ Maintenance	11 Sept.
	Parameters to	bo ellecked	Remarks
Pavement	No.	The State of the second	
Road Junction condition		~370	
Condition of Surfacing		~8/U	
		-3 70	
		·8/U	
Whether free from defects such as visible cracks, exposed		Yes/No	
Contraction Joints provided or not (CC Pavement)		Yes/No	
Compaction of flank/slope & raincuts if any		Yes/No .	
Cross Drain	age		
		ipe culverts including its painting	₩8/SRI/U
		~S/SRI/U	
Condition of railings/slab/approach for Bridges		≻8/SRI/U	
Market State Committee Com			
stones/Pavement road markings are provided and maintained			
Compliance	History	· · · · · · · · · · · · · · · · · · ·	
S47 - 300 (CEO PORT)			No
	the Road: Whether freagregates in Condition of Condition	the Road: Khutha west Programme: MAINTENANCE No.: The Project: Ongoing/Completed The Road Junction condition Condition of Surfacing Riding Quality Road Camber Whether free from defects such aggregates in case of CC Pavement. Contraction Joints provided or not (Compaction of flank/slope & raince) Cross Drainage Condition of Abutment & Wing was Condition of railings/slab/approach Road Furniture Whether sign boards/informatory stones/Pavement road markings are	the Road: Whatha west Gramin Road Panel Programme: MAINTENANCE No.: Road Id No.: The Project: Ongoing/Completed/Under Maintenance The Project: Ongoing/Completed/Under Maintenance The Project: Ongoing/Completed/Under Maintenance The Project: Ongoing/Completed/Under Maintenance The Panel of the Checked Pavement Road Junction condition Condition of Surfacing Riding Quality Road Camber Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement. Contraction Joints provided or not (CC Pavement) Compaction of flank/slope & raincuts if any Cross Drainage Condition of head walls in Hume pipe culverts including its painting Condition of Abutment & Wing walls, Slab in RCC culverts Condition of railings/slab/approach for Bridges Road Furniture Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained Compliance History

Overall Rating

Satisfactory (S)	3
Satisfactory but requires Improvement (SRI)	Mark Services
Unsatisfactory (U)	

12./2.20

(Signature) AE

NAME: