FIELD INSPECTION REPORT

In			TION REPORT	
Dist	of Inspection : /	9-12-20	District: Buxas	
			A CONTRACT OF STREET AND ADDRESS OF THE PARTY OF THE PART	
The second second	me/Programme:	HBH to Kis	agas Tola	
Pack	age No.:	MAINTENANCE	Road Id No.:	
Statu	s of the Project:	Ongoing/Completed		ted
Work	is a case of:	Ongoing/Completed/Under Maintenance Completed New Connectivity/Up gradation/ Maintenance		
SI. N	0.	Parameters to	have not to be a section of the second managed desired, on the same and construction of the property of motion before a	Remarks
1.	Pavement	The same of the sa	na da	A design to a second design of the second design of
a)	Road Junction condition			S/U 5
6)	Condition of Surfacing			S/U S
c)	Riding Quality			SAU S
d)	Road Camber			8/10 \$
e)	Whether free aggregates in ca	YES/No		
0	Contraction Joints provided or not (CC Pavement)			Yes/No
g)	Com; action of flank/slope & raincuts if any			Yes/No
1	Cross Drainage			and the second
a)	Condition of head walls in Hume pipe culverts including its painting			S/SRI/U NA
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/UNA
c) .	The state of the s			S/SRI/UNA
3.	Roud Furulture			
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			Yes/No
6	Compliante Hist		and the section of th	The same of the sa
)	Status of ATR's & any others			NO

Overall Rating

Satisfactory (S)	S
Sa is factory but requires Improvement (SRI)	and the street interest the property of property of the street of the st
Unantisfactory (U)	

legely 20

(Signature)

NAME:

DESIGNATION: