

(60) Old M/R

FIELD INSPECTION REPORT

Date of Inspection : 23.12.2020		District: Ara
Division : Ara		Length (km): 2.00 km
Name of the Road: Kollur Baidung p.p. Road to Manabpur		
Scheme/Programme: MAINTENANCE		Road Id No.: 10491608158
Package No.:		
Status of the Project: Ongoing/Completed/Under Maintenance		
Work is a case of: New Connectivity/Up gradation/ Maintenance		

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	S/U ✓
a)	Road Junction condition	S/U ✓
b)	Condition of Surfacing	S/U ✓
c)	Riding Quality	S/U ✓
d)	Road Camber	S/U ✓
e)	Whether free from defects such as visible cracks, aggregates in case of CC Pavement.	exposed Yes/No ✓
f)	Contraction Joints provided or not (CC Pavement)	Yes/No ✓
g)	Compaction of flank/slope & raincuts if any	Yes/No ✓
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U } N.A.
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U }
c)	Condition of railings/slab/approach for Bridges	S/SRI/U }
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & stones/Pavement road markings are provided and maintained	200m Yes/No ✓
4.	Compliance History	
a)	Status of ATR's & any others	NIL

Overall Rating :

Satisfactory (S)

Satisfactory but requires Improvement (SRI)

Unsatisfactory (U)

(U)

Remarks: Damaged throughout. The road is being made motorable by filling in brickbats at present.

NAME:

Rectification done or not: Not
Rectification is started or not: Not
Notice issued or not: Not

(Signature)

28/12/20

EE

(N.A. ISHRAAT)