

FIELD INSPECTION REPORT

Date of Inspection : 19/12/2020 District: Banke
 Division : Banke-1 Length (km): 1.079 km
 Name of the Road: Banke Belhar Road Bengalore More to Bengalore
 Scheme/Programme: MAINTENANCE
 Package No.: Road Id No.:
 Status of the Project: Ongoing/Completed/Under Maintenance
 Work is a case of: New Connectivity / Up gradation/ Maintenance

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
	Road Junction condition	✓ S/L
	Condition of Surfacing	✓ S/L
	Riding Quality	✓ S/L
	Road Camber	✓ S/L
	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	✓ Yes/No
	Contraction Joints provided or not (CC Pavement)	✓ Yes/No
	Compaction of flank/slope & raincuts if any	✓ Yes/No
2.	Cross Drainage	
	Condition of head walls in Hume pipe culverts including its painting	✓ S SRI U
	Condition of Abutment & Wing walls, Slab in RCC culverts	S SRI U NA
	Condition of railings/slab/approach for Bridges	S SRI U NA
3.	Road Furniture	
	Whether sign boards/informatory/cautionary Board km & 200m times Pavement road markings are provided and maintained	✓ Yes/No
4.	Compliance History	
	Zone of A.I.V. & any others	

Satisfactory (S)

Satisfactory but requires Improvement (SRI)

Unsatisfactory (U)

Pratik
24/12/2020

(Signature)

NAMU ASHOK KUMAR SINHA

JUNIOR ENGINEER