FIELD INSPECTION REPORT

Date of Inspection: 21-12-2020			District: Nalanda		
Division: Haman			Length (km): 0.980		
		H- 31 TO H	esanchak		
		MAINTENANCE	, , , , , , , , , , , , , , , , , , , ,		
Package No.:			Road Id No.:		
			ed/Under Maintenance		
	a case of:	New Connectivity	/Up gradation/ Maintenance		
SI. No.	Parameters to be checked			Remarks	
1.	Pavement				
a)	Road Junction condition			S/U	
b)	Condition of Surfacing			√S/U	
c)	Riding Quality			√S/U	
d)	Road Camber			S/U	
c)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement. Yes/No				
Ŋ	Contraction Joints provided or not (CC Pavement)			Yes/No	
g)	Compaction of flank/slope & raincuts if any			¥es/No	
2.	Cross Drainage				
a)	Condition of head walls in Hume pipe culverts including its painting 8/8			S/SRI/U	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/U	
c)	Condition of railings/slab/approach for Bridges			S/SRI/U	
3.	Road Furniture				
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained.				
4.15	Compliance History				
a)	Status of ATR's & any others				

Overall Rating

Satisfactory (S)	91
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

(Signature)

NAME: murest par sigh

DESIGNATION: A.E