## FIELD INSPECTION REPORT

Date of Inspection: 21-12-2020			District: Nalanda		
Division: Haman			Length (km): 1-500		
Name of	the Rond: B.	ena mubarka	in poli de Pulizai T	o tarbigh	
Scheme/	Programme:	MAINTENANCE		Paragraphy Williams	
Package No.:			Road Id No.:	(A) 的数据数据	
Status of	the Project:	Ongoing/Complete	ed/Under Maintenance	(1) 10 mm (1) 1	
Work is	a case of:	New Connectivity	/Up gradation/ Maintenance		
SI. No.	Parameters to be checked			Remarks	
1.	Pavement				
n)	Road Junction condition			√8/U	
b)	Condition of Surfacing			√S/U	
c)	Riding Quality			√8/U	
d)	Road Camber			√S/U	
c)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes/No	
f)	Contraction Joints provided or not (CC Pavement)			Yes/No	
g)	Compaction of flank/slope & raincuts if any			¥es/No	
2.	Cross Drainage				
a)	Condition of head walls in Hume pipe culverts including its painting			S/SRI/U	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/U	
c)	Condition of railings/slab/approach for Bridges			S/SRI/U	
3.	Road Furniture				
<b>a</b> )	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained Yes/No				
4.	Compliance History			1.4	
a)	Status of ATR's & any others				

Overall Rating

(9)

(Signature)

Millery

NAME: mulel Korgiy

DESIGNATION: AFE