FIELD INSPECTION REPORT

Date of I	nspection:	21-12-2020	District: Nalanda	SANT WEST	
Division: Hogran			Length (km): 1000		
Name of	the Rond:	ero unha	Pricesy To Shir mardin	r south sol	
	Programme: "	MAINTENANCE			
Package No.:			Road Id No.:		
	the Project:		led/Under Maintenance	A MANAGEMENT OF THE SECOND	
	a case of:		/Up gradation/ Maintenance		
Sl. No.	Parameters to be checked			Remarks	
1.	Pavement				
n)	Road Junction condition			√8/U	
b)	Condition of Surfacing			√8/U	
c)	Riding Quality			√S/U	
d)	Road Camber			√S/U	
c)	Whether free	Yes/No			
Ŋ	Contraction Joints provided or not (CC Pavement)			Xes/No	
g)	Compaction of flank/slope & raincuts if any			Yes/No	
2.,	Cross Drainage				
a)	Condition of head walls in Hume pipe culverts including its painting			S/SRI/U	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/U	
c)	Condition of railings/slab/approach for Bridges			S/SRI/U	
3.	Road Furniture				
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			Yes/No	
4.5	Compliance History				
a)	Status of ATR's & any others				

Overall Rating

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	'SRI'
Unsatisfactory (U)	2 2-4 LE 10 10 10 10 10 10 10 10 10 10 10 10 10

(Signature)

NAME: much per sigh

DESIGNATION: A.E