FIELD INSPECTION REPORT

		TOPPO HOTEL	TION REPORT	
Dat	e of Inspection : /:	2.12.2020	District: SAMASTIPUA	,
Divi	ision: SAM,	ASTEPUR	Length (km): 0 4 0 16	
	ne of the Road:	Top bacchwii	Ko aboy A Muxaca C	lowk war
	eme/Programme:	MAINTENANCE	Ke July to margine	COCK
		1G57 (SC)	Road Id No.:	
			Ongoing/Completed/Under Maintenance M New Connectivity/Up gradation/ Maintenance	
Work is a case of:				
SI. I	Va	Parameters to b	oe checked	Remarks
1,	Payement	general production		
a)	Road Junction	condition		S/U
b)	Condition of St	urfacing		S/U
c)	Riding Quality			S/U
d)	Road Camber		1	S/U
e)		from defects such se of CC Pavement.	as visible cracks, exposed	Yes/No
f)	Contraction Join	nts provided or not (CC	Pavement)	Yes/No
g)	Compaction of I	lank/slope & raincuts	if any	Yes/No
Ž.	Cross Drainage			
a)	Condition of hea	d walls in Hume pipe	culverts including its painting	š/sri/u
b)	Condition of Abi	itinent & Wing walls,	Slab in RCC culverts	S/SRI/U
2)	Condition of raili	ngs/slab/approach for	Bridges	S/SRI/U
	Road Furniture			A Section of the Control of the Cont
)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			Yes/No
	Compliance Histo	ory .		NIL
	Status of ATR's &	any others		MIL
1		the state of the s		

Overall Rating

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

Syavan 21.12.20 (Signature)