FIELD INSPECTION REPORT

Date of	Inspection:	21-12-2020	District: Natanda	2 1 1 1 10 10
District			Length (km): 0.930	
Name of	the Rond: NY	1-31 the Adordh	To Hole has short sidy	Midra
	- regionization	MAINTENANCE		Agricultura esta
Package No.:			Road Id No.:	
			ed/Under Maintenance	
	n case of:		/Up gradation/ Maintenance	
SI. No.	Parameters to be checked			Remarks
1.	Pavement			
a)	Road Junction condition			√S/U
b)	Condition of Surfacing			∠S/U
c)	Riding Quality			∠8/U
d)	Road Camber			∠8/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes/No
Ŋ	Contraction Joints provided or not (CC Pavement)			Xes/No
g)	Compaction of flank/slope & raincuts if any			Yes/No
2.	Cross Drainage			
a)	Condition of head walls in Hume pipe culverts including its painting			S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts S.			S/SRI/U
c)	Condition of railings/slab/approach for Bridges			S/SRI/U
3.	Road Furniture			
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			Yes/No
14.	Compliance History			-
a)	Status of ATR	L's & any others	The second second second to	

Overall Rating

Satisfactory (S)

Satisfactory but requires Improvement (SRI)

Unsatisfactory (U)

(Signature)

NAME: muchest kummer Sight

DESIGNATION: AFE

Scanned with CamScanner