

FIELD INSPECTION REPORT

Date of Inspection : 19.12.2020 District: Kaimur (Bhabhua)
 Division : Mohua Length (km):
 Name of the Road: Daula NH 30 TO MAJHARI NH 2
 Scheme/Programme: MAINTENANCE
 Package No.: Road Id No.:
 Status of the Project: Ongoing/Completed/Under Maintenance
 Work is a case of: New Connectivity/Up gradation/ Maintenance

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a.	Road Junction condition	SI
b.	Condition of Surfacing	SI ✓
c.	Riding Quality	SI
d.	Road Camber	SI
e.	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No ✓
f.	Contraction Joints provided or not (CC Pavement)	Yes/No ✓
g.	Compaction of flank slope & raincuts if any	Yes/No ✓
2.	Cross Drainage	
a.	Condition of head walls in Hume pipe culverts including its painting	S/SRI
b.	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI
c.	Condition of railings/slab approach for Bridges	S/SRI
3.	Road Furniture	
a.	Whether sign boards/informatory/cautionary Board km & 200m stones Pavement road markings are provided and maintained	Yes/No ✓
4.	Compliance History	
a.	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)

Satisfactory but requires Improvement (SRI) ✓

Unsatisfactory (U)

Some pot hole are visible and bush cutting required.

27/02/2021
 (Signature) 19.12.2020

NAME: Ex. Arun Kumar Mahto